SYMBOL DEFINITION		MISSING SYMBOLS
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL ☐ DOES NOT REQUIRE INSPECTION, IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.	TOTAL NO OF INSPECTIONS REQUIRED: 9	NO MISSING SYMBOL NUMBER
	LAST NO. USED: 9	

DWG STATUS						ZONE	REVISION HISTORY	AUTH	DR	APVD	APVD
DATE	STS	REV	PVP	CHG							
08SE21	R	01	-	-			INITIAL RELEASE	447070	HARI	MAD	HSB
17SE21	R	01	AA				BOM TABLE UPDATED	447070	HARI	MAD	HSB
28SE21	R	01	AB		B14		SHEET FRAME SIZE REDUCED TERMINAL TABLE UPDATED	447070	HARI	MH	HSB
15DE21	R	01	AC			A4	PROCESS SENSITIVE DIMENSION CHANGED	447070	HARI	ZX	MH

| PART-NO | CAVITY | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50 | 51 | 52 | 53 | 54 | 55 | 56 | 57 | 58 | 59 | 60 | 61 | 62 | 63 | 64 | 65 | 66 | 67 | 68 | 69 | 70 | 71 | 72 | 73 | 74 | 75 | 76 | 77 | 78 | 79 | 80 | 81 | 82 | 83 | 84 | 85 | 86 | 87 | 88 | 89 | 90 | 91 |
|---|---|---|---|---|---|---|---|---|---|---|---