ADDITIONAL ASSEMBLY INFORMATION

THE ASSEMBLY SHOWN ON THIS DRAWING REQUIRE THE USE OF MULTICORE CABLE. FERRULES MUST BE LOCATED AS SHOWN WHEN CRIMPED WITH RESPECT TO THE TERMINAL.



EXPLODED VIEW FOR CABLE ASSEMBLY



i2	1	RETAINER	PBT GF20	ORANGE	331.39029	-
i1	2	SQUEEZING SHELL	PBT GF20	ORANGE	331.39027	-
i0	1	CABLE SEAL	SILICONE	BLUE	331.39024	-
9	1	OUTER FERRULE	BRASS ALLOY	-	331.39023	-
8	1	INNER FERRULE	COPPER ALLOY	-	331.39022	-
7	3	CTS 2.8 FEMALE TERMINAL	COPPER ALLOY	-	1.394.993.3 (Sn) / 1.3882.331.9 (Ag)	-
6	2	SHIELDING CAN	BRASS ALLOY	-	331.39021	-
5	1	INNER HOUSING	PBT GF20	ORANGE	331.39056	-
REP.	QTY	DESCRIPTION	MATERIAL	COLOR	COMPONENT P/N REMARK	

CRIMPING INFORMATION

CAVITY NAME	TERMINAL	CABLE SIZE	CONDUCTOR CRIMP HEIGHT	CONDUCTOR CRIMP WIDTH	INSULATION CRIMP HEIGHT	INSULATION CRIMP HEIGHT
1-3	1.394.993.3 OR EQUIVALENT	3 MM²	2.1±0.05	3.1±0.1	4±0.08	4.2±0.08

PRINTED TUESDAY
3 1 3 9 0 4 7
A1=5 | 5:1 | 2 OF 2 | 11 OF 11 | P | 04:1









CODING OPTIONS







SECTION A - A



SECTION B-B

						331.51880	TYPE 133 (UNACTIVE)
						331.39046	TYPE 132 (SPU ACTIVE)
						331.39045	TYPE 131 (SPP ACTIVE)
i2	1	1	1	RETAINER	PBT GF20	ORANGE	331.39029 -
i1	2	2	2	SQUEEZING SHELL	PBT GF20	ORANGE	331.39027 -
i0	1	1	1	CABLE SEAL	SILICONE	BLUE	331.39024 -
9	1	1	1	OUTER FERRULE	BRASS ALLOY	-	331.39023 -
8	1	1	1	INNER FERRULE	COPPER ALLOY	-	331.39022 -
7	3	3	3	CTS 2.8 FEMALE TERMINAL	COPPER ALLOY	-	1.394.993.3 (Sn) / 1.3882.331.9 (Ag) -
6	2	2	2	SHIELDING CAN	BRASS ALLOY	-	331.39021 -
5	1	1	1	INNER HOUSING	PBT GF20	ORANGE	331.39056 -
4	1	1	1	CPA	PBT GF20	NATURAL	
3	1	1	1	SEAL RETAINER	PBT GF20	NATURAL	
2	1	1	1	CONN. SEAL	SILICONE	DARK GRAY	331.62592 (TYPE 103) -
	1	-	-	OUTER HOUSING TYPE 103			331.62591 (TYPE 102)
1	-	1	-	OUTER HOUSING TYPE 102	PBT GF20	ORANGE	331.62590 (TYPE 101)
	-	-	1	OUTER HOUSING TYPE 101			
REP.	QTY		DESCRIPTION	MATERIAL	COLOR	COMPONENT/ASSEMBLY P/N	REMARK

PRINTED TUESDAY
3 1 3 9 0 4 7
A1=5 | 5:1 | 1 OF 2 | 11 OF 11 | P | 04:1



CPA PRE-LOCK CONDITION



CPA FINAL-LOCK CONDITION

SYMBOL DEFINITION	NO. MISSING SYMBOL NUMBER
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL (A OR B) DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.	TOTAL NO OF INSPECTIONS REQUIRED: 30
INDICATES THE DIMENSION IS SHOWN ON THE PART DRAWING AND THE TOOL MUST BE QUALIFIED AT BOTH THE TOLERANCE SHOWN UNLESS SUPERSEDED BY A "(B)".	LAST NO. INSPECTION: 29



| REVISION HISTORY | | | | | | |