















































SYMBOL DEFINITION		NOTES:
A = DIMENSIONAL & VISUAL INSPECTION REPORT SYMBOL B = DIMENSIONAL INSPECTION REPORT SYMBOL TOOLING=USE THE TOOLS/LOCAL COMPONENT OFFSETS	TOTAL NO. OF SYMBOLS REQUIRED: 23 LAST NO. USED: 69	REFER TO DRAWING NOTES FOR ADDITIONAL NOTES

| REVISION HISTORY | | |