



5. TERMINALS REMOVED FROM BANDOLIER FOR INSPECTION OR SOLDERABILITY TESTS MUST BE EITHER REPLACED OR SPLICE THE BANDOLIER TOGETHER ACCORDINGLY.

<div style="text-align: center;"> <h1>• APTIV •</h1> <h2>CONNECTION SYSTEM</h2> <p>WARM, ON</p> <p>COPYRIGHT 1998 APTIV, A SONY PIONEER, INC.</p> <p>THIS DRAWING IS THE PROPERTY OF APTIV AND CONTAINS APTIV INFORMATION. IT IS TO BE KEPT CONFIDENTIAL AND NOT TO BE REPRODUCED OR UTILIZATION OF THIS DOCUMENT OR THE RELATED OR CONTAINED INFORMATION, AS WELL AS COMMUNICATION OF THE SAME OR DISCLOSURE TO OTHERS, WITHOUT EXPRESS AUTHORIZATION, IS PROHIBITED.</p> </div>									
DATE									
DR									
APPROV: JOE SUDIK						25APR94			
APPROV: JOE KIMURA						25APR94			
APPROV: M. CUMMINGS						25APR94			
APPROV: M									
SUBSTANCES OF CONCERN AND RECYCLED CONTENT(S) (DRAWING)									
MATERIAL SHEET CHART									
DRAWING NAME TAXI TERM M M/P 280									
DRAWING NUMBER <div style="font-size: 2em; font-weight: bold; text-align: center;">12160747</div>									
SIZE		SCALE		1		THICK		2	
A1x3		10:1		1 OF 2		1 OF 1		R 02	