










SYMBOL DEFINITION			
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.			24
TOTAL NO OF INSPECTIONS REQUIRED			16
LAST NO. USED			

MISSING SYMBOLS		DWG STATUS					ZONE	REVISION HISTORY				AUTH	DR	APVD	APVD					
NO MISSING SYMBOL NUMBER		DATE	STG	REV	N/P	CHG														
		30AP07	R	01	-	-	RELEASED										401241	AZ	OY	OY
		10AP08	R	02	-	-	DIM #4 WAS 21.4+/-0.2 DIM #5 WAS 25.4+/-0.2 ADD NOTE 3 TERMINAL INFORMATION										404345	WDZ	JWG	JWG
		29AP08	R	03	-	-	UPDATED PDM ATTRIBUTES										404528	WOS	JWG	EZ
		15AU08	R	03	AA	-	DIM #1 WAS 21.4+/-0.2										405766	WOS	JEG	EZ
		17JU09	R	03	AB	-	UPDATE PDM ATTRIBUTES										408256	JC	JWG	EZ
		14SE12	R	04	-	-	UPDATE PDM ATTRIBUTES										418966	AM	JWG	EZ
		15N023	R	05	-	-	ADD NEW PN 35821317. ADD DIM #15, #16.										451289	ZML	HW	JZ



NOTES

- UNLESS OTHERWISE SPECIFIED AND/OR INDICATED:

DIMENSIONS ARE TO FACE OF VIEW SHOWN AND AUTOMATICALLY ROUNDED BY COMPUTER FOR INSPECTION (SEE MATH MODEL FOR PRECISE DIMENSIONS). FOR ALL OTHER DIMENSIONS NOT SHOWN BUT REQUIRED FOR TOOL BUILD, SEE MATH MODEL FOR PRECISE TOOL PATH DATA.

- REFERENCE MATING COMPONENTS OR EQUIVALENT:
CONNECTOR ASSEMBLY: 13598001/13598002/13644843

- DIM #1 MEASURE AT POINT A AND B.
DIM #2 MEASURE AT POINT C AND D.

		10 PROCESS SENSITIVE DIMENSION									
		DIMENSIONS ENCLOSED IN () INDICATE REFERENCE DIMENSIONS AND NO TOLERANCE LIMITS ARE ESTABLISHED									
DIMENSIONAL RANGE (MM)		CHART E1									
FROM	TO	> 0	> 30	> 70	> 100	> 150	> 200	> 250	> 300	> 400	
		0	30	70	100	150	200	250	300	400	
TOLERANCE UNLESS OTHERWISE SPECIFIED											
		±0.15	±0.2	±0.3	±0.4	±0.5	±0.6	±0.8	±1	±1.2	
ANGULAR TOLERANCE ±2°											